

**Illogan Sports Ground (Changing Rooms)**

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Away Team Changing Room						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Away Team Kit Room						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Away Team Shower						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Entrance Area						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Externals						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

**Illogan Sports Ground (Changing Rooms)**

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Home Team Changing Room						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Home Team Kit Room						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Home Team Shower						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas



<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Kitchen						

Sample Ref. No:	1/0/-/P	
Material Location:	Presumed flashguards within electrical box on wall	
Approx. Quantity (m <sup>2</sup> ):	Unknown	
Accessibility:	Low	
<b>Material Assessment Score</b>		<b>Score</b>
Product Type:	Presumed asbestos textile	2
Condition:	Presumed good	0
Treatment:	Enclosed	1
Asbestos Type:	Presumed chrysotile	1
Total:		4
Comments:		



Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	-
<b>Room Description:</b>	Loft Space						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas

**Illogan Sports Ground (Changing Rooms)**

<b>UPRN:</b>	-	<b>Block No.</b>	1	<b>Floor No.</b>	0	<b>Room No.</b>	<b>Officials</b>
<b>Room Description:</b>	Officials Changing Area						

No Asbestos Detected

Areas which are concealed and have not been accessed during the survey (e.g. ceiling voids above fixed ceilings, floor and wall voids, fire doors, electric boxes, gaskets etc) and any other inaccessible area may contain asbestos. A more intrusive inspection should be carried out before working in these areas